

529-056 AQUARIUM RAINFOREST GLAZING REPLACEMENT

PIER 3

THE RAINFOREST GLAZING IS TO BE REPLACED. THE GLAZING PANELS HAVE FOGGED FROM FAILED SEALS AND THE DRAINAGE SYSTEM HAS BEEN COMPROMISED RESULTING IN LEAKS. THE STRUCTURAL SYSTEM OF THE RAINFOREST PYRAMID SKYLIGHT IS TO BE MODIFIED.

SOURCE OF FUNDS	TO DATE	REQUEST	PLANNING	FINANCE	BD OF EST	ADD-L	TOTAL
908 OTHER PRIVATE FUNDS & GRANTS		150	150	150	150	2,000	2,150
** TOTAL **		150	150	150	150	2,000	2,150